

WIRING DIAGRAM
ELECTRIC STARTER