
1953-60 Pickup Truck Outside Door Handle



The shorter screw is for 1957-1960 applications using this hole.